

Project Name: Chase Bank CHQ142248 Night Vue Ammon ID
P429419 38

Project Images:
12

Project Address: 1711 South 25th East, Ammon, ID 83406

Project Date:
02-12-2020

Survey Result

1. How would you rate the overall condition of the entire premises you visited?

Please be mindful that this question refers to all areas and/or objects at the place you visited.

☆☆☆★☆☆ **Good**

2. How does the overall condition of the premises you visited compare to similar nearby premises?

☆☆★☆☆ **Equivalent**

3. Do you agree or disagree with the following statement?

The overall condition of the entire premises you visited is inviting/appealing to customers and passersby.

☆☆☆★☆☆ **Somewhat Agree**

4. Do you agree or disagree with the following statement?

The overall condition of the entire premises you visited presents a favorable image of the brand with which it is associated.

☆☆☆★☆☆ **Somewhat Agree**

5. Do you agree or disagree with the following statement?

The overall condition of the entire premises you visited creates an environment you would choose to frequent and/or you would recommend to friends.

☆☆☆★☆☆ **Somewhat Agree**

6. Do you agree or disagree with the following statement?

The overall condition of the entire premises you visited presents the impression that the care and maintenance of the premises is of high priority to those who manage it.

☆☆☆★☆☆ **Somewhat Agree**
